

Production: Airence-Telco

Modification to correct for varying coil voltage to relay RL2.

1. Replace the following components during assembly of the PCB.

Part	Old Part	Old Part Number	New Part	New Part number
R6	820	10350728	470	10350725
Z6	8V2 Zener	10250352	9V1 Zener	10250373

The components are marked with a red cirkel

