

AIRMATE^{USB}

Question:

My Airmate generates a hum at the headphone and other outputs. How can we fix this?

Answer:

This is probably because the bridge rectifier D1 in the Airmate is defective.

We use a 2KBB100 bridge rectifier as replacement part.

Replacing this must eliminate the hum.

If you still hear some hum left it sometimes helps when you loose the screw of the transformer and slowly turn the transformer to the point of minimal hum. (be carefull with the wiring).

